



Attorney Docket No. 1793.1066
CofC

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Seung-Chul PARK et al.

Application No.: 10/766,946

ATTENTION

Confirmation No.: 2489

CERTIFICATE OF CORRECTION

Filed: January 30, 2004

BRANCH

U.S. Patent No.: 7,203,029

Issued: April 10, 2007

For: METHOD AND APPARATUS FOR CONTROLLING TRACK SEEK SERVO OF DISK
DRIVE

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:

Patentees respectfully request that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistakes shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: 21, 2007

By: Gene M. Garner, II
Gene M. Garner, II
Registration No. 34,172

1201 New York Ave, N.W., 7th Floor
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

*Certificate
of Correction
JUN 25 2007*

JUN 26 2007

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 7,203,029

DATED : April 10, 2007

INVENTOR(S) : Seung-Chul PARK et al.

First Page, Column 2 (Other Publications), Line 1, before "The" insert --Examiner Ressenaar, J-P,--.

Column 10, Line 44, change "KaI_a," to --K_a, I_a,--.Column 11, Line 59, change "KaI_a," to --K_a, I_a,--.Column 13, Line 19, change "KaI_a," to --K_a, I_a,--.Column 14, Line 47, change "KaI_a," to --K_a, I_a,--.

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP
1201 New York Ave., N.W.
7th Floor
Washington, DC 20005PATENT NO. 7,203,029No. of add'l copies
@ 50¢ per page

⇒

JUN 26 2007